



Weasler®

***LACK OF GREASE
50° CV BALL & SOCKET***

These pictures show examples of damage caused by a lack of grease in a 50° constant velocity (CV) joint ball and socket.



SOCKET YOKE



BALL YOKE