



Weasler®

**LACK OF GREASE
CROSS & BEARING KIT**

These pictures show examples of damage caused by a lack of grease in the cross and bearing kit.



TRUNION & YOKE EAR



TRUNION & YOKE EAR



TRUNION



TRUNION

Weasler Engineering, Inc.
P.O. Box 558, West Bend, WI 53095 USA
Tel: +1-262.338.2161, Fax: +1-262.338.3709
E-mail: oemsales@weasler.com
web site: www.weasler.com

Weasler Engineering BV
P.O. Box 266, 6600 AG, Wijchen, The Netherlands
Tel: +31-24-64 89 100, Fax: +31-24-64 89 109
E-mail: sales@weasler.nl
web site: www.weasler.nl

Weasler Engineering Kft
P.O. Box 262, H6001, Kecskemet, Hungary
Tel: +36-76-500410, Fax: +36-76-500 415
E-mail: sales@weasler.hu